



# Lead and copper water testing 2018

MAY 5, 2018    UPDATED 8-30-18



# Greenfield Elementary School

- ▶ 119 water sources tested
- ▶ 6 positive test results
- ▶ 0 positive results in *drinking specific* fixtures
- ▶ 0 positive results in foodservice kitchen area
- ▶ 0 positive results in large volume samples



# G10-CF Room 104

**SINK ONLY**     bubbler (fountain) tested negative

Copper    0.55 mg/L

Lead       0.0017 mg/L     **(was) 0.017 mg/L**



Removed from service for repair 5/6/18. Remediation and retesting of faucet complete. Retested and passed 5-22-18.

# G39-CF Room 103

**SINK ONLY** bubbler (fountain) tested negative

Copper 1.2 mg/L (**was 1.9 mg/L**)

Lead 0.0059 mg/l

Removed from service for repair 5/6/18. Remediation and retesting of faucet complete. Retested and passed 5-22-18.





# G45-CF Room 101

**SINK ONLY** bubbler (fountain) tested negative

Copper 0.71 mg/L

Lead 0.0014 mg/L **(was 0.016 mg/L)**



Removed from service for repair 5/6/18. Remediation and retesting of faucet complete. Retested and passed 5-22-18.

# G75-CF Room 207

**SINK ONLY** bubbler (fountain) tested negative

Copper 0.64 mg/L

Lead <0.0010 mg/L **(was 0.017 mg/L)**



Removed from service for repair 5/6/18. Remediation and retesting of faucet complete. Retested and passed 5-22-18.



# G81-CF Room 210

**SINK ONLY**     bubbler (fountain) tested negative

Copper     0.49 mg/L     0.32 mg/L

Lead     **0.035 mg/L**     0.012 mg/L

Picture  
Not  
Available

Removed from service for repair 5/7/18. Remediated and aerator replaced.  
Returned to service 8-30-18.



# G85-CF Room 200

**SINK ONLY** bubbler (fountain) tested negative

Copper 0.77 mg/L

Lead 0.0041 mg/L **(was 0.058 mg/L)**

Picture  
Not  
Available

Removed from service for repair 5/6/18. Remediation and retesting of faucet complete. Retested and passed 5-22-18.