



Lead and copper water testing 2016/17

JANUARY 14, 2017

Pierce Elementary School

- ▶ 96 water sources tested
- ▶ 18 positive test results
- ▶ 0 positive results in *drinking specific* fixtures
- ▶ 1 positive results in foodservice kitchen area (**not a food source**)
- ▶ 0 positive results in large volume samples

P05-KF P06-KF Kitchen Area

Left and middle sinks – wash area only

Copper 1) N/A mg/L 2) N/A mg/L

Lead 1) 0.047 mg/L 2) 0.030 mg/L



Faucets, Supply Lines, Valves replaced. February 2017. Retested 5-13-17 Failed
Additional plumbing replaced July 2017. Retested August 2017 - PASSED

P13-BF

Girls (admin hall)

Right sink only

Copper 1.6 mg/L

Lead N/A mg/L



Aerator changed

January 2017.

Re-test 1-28-17 passed

P14-BF Clinic

Copper 5.1 mg/L
Lead N/A mg/L

Aerator changed

January 2017.

Re-test 1-28-17 passed



P18-CF Room 113

SINK ONLY bubbler (fountain) tested negative

Copper 2.8 mg/L

Lead N/A mg/L



Aerator changed

January 2017.

Re-test 1-28-17 passed

P25-CF Room 111 (bathroom)

Copper 1.5 mg/L
Lead N/A mg/L



Aerator changed

January 2017.

Re-test 1-28-17 passed

P33-DS Custodial area

Copper 1.6 mg/L
Lead 0.021 mg/L



Permanently signed as “Not Drinking Water” August 2017

P42-CF Room 105a

Copper N/A mg/L
Lead 0.017 mg/L



Aerator changed

January 2017.

Re-test 1-28-17 passed

P50-CF Room 101

Copper 4.7 mg/L

Lead N/A mg/L



Aerator changed

January 2017.

Re-test 1-28-17 passed

P56-BF

Boys bathroom (by 205)

Left sink only

Copper 2.8 mg/L

Lead 0.019 mg/L



Faucet, supply lines, and valves replaced. February 2017. Retested 5-13-17 PASSED

P61-BF

Girls bathroom (by 205)

Right sink only

Copper N/A mg/L

Lead 0.024 mg/L



Aerator changed

January 2017.

Re-test 1-28-17 passed

P79-BF

Girls bathroom (by 216)

Left sink only

Copper 1.3 mg/L

Lead N/A mg/L



Aerator changed

January 2017.

Re-test 1-28-17 passed

P84-BF

Boys bathroom (by 216)

Right sink only

Copper 1.5 mg/L

Lead N/A mg/L



Aerator changed

January 2017.

Re-test 1-28-17 passed

P85-CF Room 218

SINK ONLY bubbler (fountain) tested negative

Copper 1.6 mg/L

Lead N/A mg/L



Aerator changed

January 2017.

Re-test 1-28-17 passed

P87-DS Custodial area

Copper N/A mg/L
Lead 0.018 mg/L



Permanently signed as "Not Drinking Water" August 2017

P91-CF Room 105

Copper 2.3 mg/L
Lead N/A mg/L



Aerator changed

January 2017.

Re-test 1-28-17 passed

P93-CF Room 103

SINK ONLY bubbler (fountain) tested negative

Copper N/A mg/L

Lead 0.028 mg/L



Faucet, Supply lines, & Valves replaced 3/2017. Retested 5-13-17 PASSED

P95-CF Room 206

Copper N/A mg/L
Lead 0.019 mg/L



Faucet, Supply lines, & Valves replaced 3/2017. Retested 5-18-17 PASSED